


2/5

Fig.2






Fig.3




Fig.4

5/5

BEST AVAILABLE COPY

Fig.5

OmniBER XM: session 4 (rtaylor) on kmtest03

File Tools Help

Ports: Add On Off

Configuration: Hide Show

Gating: Setup

Continuous

Start Stop

Help

Overview

E+A

OH

Counts

GR-253

G.828

SRV-DIS

J1 Trace

Start Test

On selected port only

Port

Mismatches

203/1

204/1

0

Channel	Result	Length	Expected J1 Path Trace	Measured J1 Path Trace	Length
1.1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-001	Agilent OmniBER XM J7241A Port 0204/1-001	64 Bytes
17.1	Fail	64 Bytes	Should fail	Agilent OmniBER XM J7241A Port 0204/1-049	64 Bytes
33.1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-097	Agilent OmniBER XM J7241A Port 0204/1-097	64 Bytes
37.1	Not Tested	64 Bytes	Not tested yet		
41.1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-121	Agilent OmniBER XM J7241A Port 0204/1-121	64 Bytes
45.1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-133	Agilent OmniBER XM J7241A Port 0204/1-133	64 Bytes
49.1	Pass	64 Bytes	Agilent OmniBER XM J7241A Port 0204/1-145	Agilent OmniBER XM J7241A Port 0204/1-145	64 Bytes

Copy Expected J1s

From:

Tx on 203/1

Current Rx

All Ports

Copy Now